

Route	Argalasti circular (via Milea Winery)
Checked by	Mandi Mathews & Janet Tindall
Date	17 September 2023
Condition	Difficult in places, passable with caution

Description of the walk

We leave Argalasti passing the schools and climbing uphill through the part of the village known as Kamara in the direction of Kallithea. The first part of the route rises steeply. There will be a short walk on the road and then we will turn left along the track behind and overlooking Argalasti - great views. We will then circle around and return to Argalasti passing the Ktima Milea Winery and Vineyard.

Condition of the walk

At several points along the walk there are gulleys which have been gauged out by the water, especially on the track back towards Argalasti (picture 1).

After ascending and turning left back towards Argalasti there is considerable damage where deep gulleys need to be negotiated with care (pictures 2, 3).

Lower down, where the stream crosses the path, the concrete track has been washed away and great care is needed at this point (pictures 4, 5).

It was not possible to check the condition of the old stone bridge as the banks of the stream have been severely damaged and it was not safe to walk down to the bridge.

[Pictures on the following pages](#)









