

**Route**                **Lafkos - Milina - Lafkos**  
**Checked by**        **David Lewis**  
**Date**                **24 September 2023**  
**Condition**         **One route passable with caution, one route not passable**

## **Description of the walk**

*Routes A and B, Lafkos - Milina and Milina - Lafkos*

## **Condition of the walk**

Photo 1: This is the top section of the main kalderimi path from Lafkos to Milina (Chorto side). As you can see from the photo, the path is still very passable but the rain has brought silt onto the path and washed off the stones from the centre of the path.

Photo 2: The middle section of the kalderimi from Lafkos to Milina, where the little chapel is located. As can be seen from the photo lots of soil/ silt has been washed down the hill and collected outside the chapel. There is also silt and water inside the chapel which will damage the floor and objects inside.

Photo 3: The middle section of the kalderimi from Lafkos to Milina, just below the above chapel. As can be seen from the photo, part of this path has been washed away, but is still passable, though potentially a little dangerous as now a relatively steep drop to the side.

Photos 4 and 5 - relate to the middle path from Milina to Lafkos- the final section from the Milina to Lafkos road to Lafkos. The first section from the edge of Milina was all passable (just silt and loose stones in parts).

Photo 4: Fallen tree across the path - whilst blocking the path, it is still possible to climb through the fallen tree.

Photo 5: This section of the path (approximately 1,000 to 1,500 m) along this section of the kalderimi, is totally blocked and inaccessible as a result of a landslide. One side of the path is a steep drop into the gully below and the other side is blocked by dense vegetation.

*[Pictures on the following pages](#)*

















