

## **Route Trikeri Agia Kyriaki**

**Checked by Dimitrios Pettas, Katerina Tzouvali**

**Date October 9 2023**

**Condition Difficult in places, passable with caution**

### **Description of the walk**

The route connects Trikeri with Agia Kyriaki, with a beautiful view of the Trikeri channel. The route starts from Trikeri, initially following the cobbled road in the village, continues for a while on the ring road, follows the old cobbled road to Agia Kyriaki, after first intersecting with the asphalt, which connects the asphalt road Trikeri Ag Kyriaki to Vigla.

### **Condition of the walk**

In some parts of the cobblestone there are large and small stones, which one can easily avoid (image 1)

At the point where the cobblestone meets the water main, the cobblestone is damaged before the storms, but there are no safety reasons (image 2)

At one point the cobblestone has collapsed but can be walked on with care (image 3)

At the end, when the cobblestone approaches Agia Kyriaki, cement has been placed between the stones, but it was not able to remain stable everywhere against the rushing waters of the storms (images 4,5,6,7,8).

In addition, the collapse of a sidewalk has brought large stones to the cobblestone (image 7)

In places, grasses have grown in the cobblestones, but they do not prevent safe passage (images 9,10,11)

Pictures on the following pages





































