

Διαδρομή Μονή Πάου - δρόμος προς Χόρτο
Ελέγχθηκε από Mandi Mathews & Janet Tindall
Ημερομηνία 1 & 3 Οκτωβρίου 2023
Κατάσταση Πλήρης κατάρρευση του μονοπατιού, δεν είναι ασφαλές να περπατήσετε

Η περιγραφή του περπατήματος

Leaving the vrisi Paou Monastery and heading down the farm track towards the road to Horto.

Πληροφορία για την κατάσταση της διαδρομής

Leaving the vrisi at Paou Monastery there is a farm track which passes two houses on the right and one on the left before going through olive groves. Towards the bottom of this track, where it used to go around a bend and then back up towards the Horto road, there is considerable damage (pictures 1, 2 and 3) and a landslide which makes this route not safe to walk.

From the other side (pictures 4, 5 & 6) the path just disappears down into the valley and is not safe to pass.

Since this time, we have been advised that some repairs have been carried out and it is possible to use this route, however it is not safe and is not suitable for anyone who does not wish to walk along a very narrow ledge above a deep gorge.

[Εικόνες στις επόμενες σελίδες](#)











